

INSPECTION REPORT


End of contract

GENERAL INFO

File	322120
License plate	2CDX278
Vehicle identification number	VXEVEHTMN7025428
Dossier	2022 073 116
Make	Opel Viv.TD 106kW L3H1 Innovat
Mileage	106673
First registration	17/06/2022
client availability date	11/09/2026
inspectionDate	22/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
35	Front Bonnet // Polish	Y
80	Door Front Left // Smart Repair Small	Y
103	Door Rear Left // Painting	Y
114	Wing Rear Left // Repair & Painting	N
181	Wing Rear Right // Smart Repair Medium	Y
304	Rear Loading Door Right // Repair & Painting	Y
860	Interior Cleaning // Small	N

Damage Pictures



Wing Rear Right // Smart Repair Medium-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Front Bonnet // Polish-scratch



Rear Loading Door Right // Repair & Painting-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Interior Cleaning // Small-dirty



Lettering Removal 15min-