

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	309918
License plate	1YVL187
Vehicle identification number	VF3MCYHZMLS282277
Dossier	2020262039
Make	Peugeot 5008 1.5BHDi 96kW Allu
Mileage	100140
First registration	04/01/2021
client availability date	05/05/2026
inspectionDate	11/05/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
113	Wing Rear Left // Painting	N
133	Bumper Rear // Painting	N
16	Bumper Front // Polish	Y
35	Front Bonnet // Polish	Y
81	Door Front Left // Smart Repair Medium	Y
91	Rocker Panel Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	N
117	Wing Rear Left / Trim / Replace	N
165	Roof // Polish	N
191	Door Rear Right // Smart Repair Medium	N
201	Rocker Panel Right // Smart Repair Medium	N
222	Side View Mirror Right // Painting	N
266	Foglight Rear // Replacement	N
310	Wheel Two Tone Front Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
860	Interior Cleaning // Small	Y

## Damage Pictures





Damage within Renta-norm-



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wing Rear Left / Trim / Replace-scratch



Foglight Rear // Replacement-scratch



Side View Mirror Right // Painting-scratch




Door Rear Right // Smart Repair Medium-dent



Rocker Panel Right // Smart Repair Medium-scratch + dent




Rocker Panel Left // Smart Repair Medium-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain



Roof // Polish-scratch





Front Bonnet // Polish-scratch



Bumper Front // Polish-scratch




Wheel Two Tone Front Left // Repair-scratch



Door Front Left // Smart Repair Medium-scratch



Wing Rear Left // Painting-scratch



Bumper Rear // Painting-scratch