

INSPECTION REPORT


End of contract

GENERAL INFO

File	320759
License plate	2CBJ777
Vehicle identification number	TMBJW7NPXN7040876
Dossier	2022111015
Make	Skoda Sup.Comb.PHEV 218 Clev.i
Mileage	145366
First registration	20/05/2022
client availability date	26/08/2026
inspectionDate	03/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
106	Door Rear Left // Polish	Y
116	Wing Rear Left // Polish	Y
12	Bumper Front // Smart Repair Large	N
80	Door Front Left // Smart Repair Small	Y
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
214	Door Front Right // Repair & Painting	Y
219	Door Front Right / Window / Replace	Y
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures




Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Front Right // Repair & Painting-scratch + dent



Bumper Rear // Polish-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Front Right / Window / Replace-scratch



Wheel Alloy Front Right // Repair-scratch





Bumper Front // Smart Repair Large-scratch



Wheel Alloy Front Left // Repair-scratch



Door Front Left // Smart Repair Small-scratch



Door Rear Left // Polish-scratch



Wing Rear Left // Polish-scratch