

INSPECTION REPORT

End of contract

GENERAL INFO

File	305744
License plate	2BAS603
Vehicle identification number	ZFANF2C31MP920648
Dossier	2021 243 070
Make	Fiat 500X 1.0 FT 120 Sport
Mileage	43003
First registration	12/09/2021
client availability date	16/02/2026
inspectionDate	04/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	








DAMAGES

Damages	Type	Acceptable
103	Door Rear Left // Painting	N
113	Wing Rear Left // Painting	N
163	Roof // Repair & Painting	Y
340	Wheel Two Tone Front Right // Repair	Y
850	Certificate of Conformity //	N
851	Registration Card loss Arval name //	N

Damage Pictures



Damage within Renta-norm-





Door Rear Left // Painting-scratch



Wing Rear Left // Painting-scratch



Wheel Two Tone Front Right // Repair-scratch



Roof // Repair & Painting-scratch + dent