

INSPECTION REPORT

End of contract

GENERAL INFO

File	307483
License plate	1YWY458
Vehicle identification number	W1K1186121N185781
Dossier	2020 199 097
Make	Mercedes CLA SB 200 d Bus.Solu
Mileage	39126
First registration	18/01/2021
client availability date	13/03/2026
inspectionDate	26/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
138	Bumper Rear / Lower Cover Not Painted / Replace	N

Damage Pictures



Damage within Renta-norm-



Bumper Rear / Lower Cover Not Painted / Replace-hole