

INSPECTION REPORT


End of contract

GENERAL INFO

File	307770
License plate	2BNJ305
Vehicle identification number	VF3MCYHZUMS267383
Dossier	2021204086
Make	Peugeot 3008 1.5BHdi 96kW Acti
Mileage	153522
First registration	24/01/2022
client availability date	16/03/2026
inspectionDate	24/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







Damage within Renta-norm-



Interior // Repair 1-scratch



Front Bonnet // Painting-rust