

INSPECTION REPORT

End of contract

GENERAL INFO

File	318209
License plate	1YXF404
Vehicle identification number	TMBJP7NX2MY063753
Dossier	2020 356 084
Make	Skoda Oct.Com.1.0 eTec 81kW Am
Mileage	121176
First registration	20/01/2021
client availability date	20/07/2026
inspectionDate	12/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
196	Door Rear Right // Polish	Y
213	Door Front Right // Painting	Y
14	Bumper Front // Repair & Painting	N
35	Front Bonnet // Polish	Y
38	Front Bonnet / Insulation / Replace	N
95	Rocker Panel Left // Polish	Y
106	Door Rear Left // Polish	Y
114	Wing Rear Left // Repair & Painting	Y
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
165	Roof // Polish	Y
186	Wing Rear Right // Polish	Y
321	Wheel Alloy Rear Left // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
773	Interior / A Pillar Lower Cover / Replace	Y
774	Interior / Side Cover rear Seat / Replace	Y
860	Interior Cleaning // Small	Y

Damage Pictures



Wheel Alloy Front Right // Repair-scratch



Front Bonnet // Polish-scratch



Door Rear Left // Polish-scratch



Rocker Panel Left // Polish-scratch



Wheel Alloy Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Interior / A Pillar Lower Cover / Replace-scratch




Roof // Smart Repair Medium-dent



Wing Rear Left // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Roof // Polish-Chemical reaction




Interior Cleaning // Small-stain



Front Bonnet / Insulation / Replace-hole



Bumper Rear // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Right // Polish-scratch



Door Rear Right // Polish-scratch



Door Front Right // Painting-scratch