

INSPECTION REPORT



End of contract

GENERAL INFO

File	314143
License plate	2CAD746
Vehicle identification number	VSSZZZKJZNR104955
Dossier	2022045014
Make	Seat Arona 1.0 81kW Move DSG
Mileage	116667
First registration	08/05/2022
client availability date	06/06/2026
inspectionDate	11/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	Y
180	Wing Rear Right // Smart Repair Small	Y
331	Wheel Alloy Rear Right // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Wheel Alloy Rear Right // Repair-scratch



Bumper Rear // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Wing Rear Right // Smart Repair Small-dent

