

INSPECTION REPORT



End of contract

GENERAL INFO

File	319619
License plate	2AMX096
Vehicle identification number	VSKCTND23U0163343
Dossier	2020209035
Make	Nissan Navara 2.3dCi DC 4x4 16
Mileage	155226
First registration	19/05/2021
client availability date	05/08/2026
inspectionDate	17/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
14	Bumper Front // Repair & Painting	N
33	Front Bonnet // Repair & Painting	N
41	Windshield // Replace	Y
54	Headlight / Front left / Replace	Y
63	Wing Front Left // Painting	Y
77	Side View Mirror Left / Shell / Replace Not Painted	Y
84	Door Front Left // Repair & Painting	N
87	Door Front Left / Trim / Replace	N
88	Door Front Left / Door Handle / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
103	Door Rear Left // Painting	N
107	Door Rear Left / Trim / Replace	N
108	Door Rear Left / Door Handle / Replace	N
114	Wing Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	N
133	Bumper Rear // Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
163	Roof // Repair & Painting	N
174	Light / Rear Right / Replace	N
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	N
198	Door Rear Right / Door Handle / Replace	N
201	Rocker Panel Right // Smart Repair Medium	N
214	Door Front Right // Repair & Painting	N
217	Door Front Right / Trim / Replace	N
218	Door Front Right / Door Handle / Replace	N
227	Side View Mirror Right / Shell / Replace Not Painted	Y

233	Wing Front right // Painting	Y
244	Light / Front Right / Replace	Y
293	Rear Loading Door Left // Painting	N
303	Rear Loading Door Right // Painting	N
411	Seat Front Left // Repair	N
412	Seat Front Left / Bottom Coating / Replace	N
413	Seat Front Left / Rear Coating / Replace	N
417	Seat Front Left / Headrest / Replace	N
421	Seat Front Right // Repair	N
422	Seat Front Right / Bottom Coating / Replace	N
423	Seat Front Right / Rear Coating / Replace	N
424	Seat Front Right / Complete Coating / Replace	N
433	Seat Rear Left / Rear Coating / Replace	N
437	Seat Rear Left / Headrest / Replace	N
452	Seat Rear Right / Bottom Coating / Replace	N
453	Seat Rear Right / Rear Coating / Replace	N
457	Seat Rear Right / Headrest / Replace	N
533	Trunk Compartment / Side Cover Right / Replace	N
534	Trunk Compartment / Carpet / Replace	N
540	Interior // Repair 1	N
540	Interior // Repair 1	N
541	Interior // Repair 2	N
543	Interior // Ionization Odor	N
551	Central Console // Repair	N
553	Central Console / Gear Lever / Replace	Y
556	Central Console / Cover Armrest / Replace Cover Armrest	N
558	Central Console / Cup Holder / Replace	N
564	Dashboard // Replace Completely	Y
565	Dashboard / Storage Tray / Replace	N
569	Dashboard / Steering Wheel / Replace	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
598	Trunk Lid Interior Coating / Handle / Replace	N
614	Front Left Door Interior Coating // Replace Completely	N
621	Front Right Door Interior Coating // Repair	N

624	Front Right Door Interior Coating // Replace Completely	N
631	Rear Left Door Interior Coating // Repair	N
634	Rear Left Door Interior Coating // Replace Completely	N
638	Rear Left Door Interior Coating / Door Handle / Replace	N
641	Rear Right Door Interior Coating // Repair	N
644	Rear Right Door Interior Coating // Replace Completely	N
772	Interior / A Pillar Upper Cover / Replace	N
773	Interior / A Pillar Lower Cover / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Light / Rear left / Replace-scratch



Light / Front Right / Replace-scratch



Headlight / Front left / Replace-scratch



Roof // Smart Repair Medium-scratch



Rocker Panel Right // Smart Repair Medium-scratch




Side View Mirror Right / Shell / Replace Not Painted-scratch



Windshield // Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch



Central Console / Gear Lever / Replace-scratch



Front Left Door Interior Coating // Replace Completely-scratch




Front Bonnet // Repair & Painting-dent



Door Front Right // Repair & Painting-dent





Wing Rear Left // Repair & Painting-scratch + dent



Roof // Repair & Painting-scratch + dent




Wing Rear Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent




Door Front Left // Repair & Painting-scratch + dent



Light / Rear Right / Replace-cracked



Bumper Front // Repair & Painting-cracked



Interior // Repair 1-Incinerated



Interior // Repair 1-stain



Front Right Door Interior Coating // Repair-stain



Front Right Door Interior Coating // Replace Completely-stain



Interior Cleaning // Small-stain



Seat Rear Left / Rear Coating / Replace-stain



Seat Front Left / Headrest / Replace-stain



Seat Front Left // Repair-stain



Rear Left Door Interior Coating // Repair-stain



Rear Left Door Interior Coating // Replace Completely-stain



Rear Left Door Interior Coating / Door Handle / Replace-stain



Door Front Left / Door Handle / Replace-stain



Door Rear Left / Door Handle / Replace-stain



Door Rear Left // Painting-stain



Dashboard / Storage Tray / Replace-stain



Interior // Repair 2-stain




Door Front Right / Trim / Replace-stain



Seat Front Right / Complete Coating / Replace-stain



Central Console / Cover Armrest / Replace Cover
Armrest-stain



Seat Front Right / Rear Coating / Replace-stain



Seat Front Right / Bottom Coating / Replace-stain



Central Console // Repair-stain



Door Front Left / Trim / Replace-stain



Interior / A Pillar Upper Cover / Replace-stain



Interior / A Pillar Lower Cover / Replace-stain



Seat Front Left / Rear Coating / Replace-stain



Seat Front Left / Bottom Coating / Replace-stain



Dashboard / Steering Wheel / Replace-stain



Wing Front Left // Painting-stain



Side View Mirror Left / Shell / Replace Not Painted-stain



Wing Front right // Painting-stain




Door Rear Right / Door Handle / Replace-stain



Door Front Right / Door Handle / Replace-stain





Door Rear Left / Trim / Replace-stain



Seat Rear Right / Headrest / Replace-stain



Seat Rear Left / Headrest / Replace-stain



Seat Rear Right / Rear Coating / Replace-stain



Seat Rear Right / Bottom Coating / Replace-stain



Door Rear Right / Trim / Replace-stain




Seat Front Right // Repair-stain



Rear Right Door Interior Coating // Replace Completely-stain



Bumper Rear // Painting-stain



Rear Loading Door Right // Painting-stain



Trunk Compartment / Carpet / Replace-stain



Trunk Compartment / Side Cover Right / Replace-stain



Trunk Lid Interior Coating / Complete Panel / Replace-stain



Rear Loading Door Left // Painting-Chipped paint



Trunk Lid Interior Coating / Handle / Replace-bad position



Rear Right Door Interior Coating // Repair-bad position



Central Console / Cup Holder / Replace-hole



Dashboard // Replace Completely-hole



Lettering Removal 15min-