



**ARVAL**  
BNP PARIBAS GROUP

2CCT866

## INSPECTION REPORT

End of contract

### GENERAL INFO

|                               |                              |
|-------------------------------|------------------------------|
| File                          | 314142                       |
| License plate                 | 2CCT866                      |
| Vehicle identification number | VSSZZZKJZNR108268            |
| Dossier                       | 2022045012                   |
| Make                          | Seat Arona 1.0 81kW Move DSG |
| Mileage                       | 110595                       |
| First registration            | 08/06/2022                   |
|                               |                              |
| client availability date      | 06/06/2026                   |
| inspectionDate                | 11/06/2026                   |

### CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                                  | Acceptable |
|---------|-------------------------------------------------------|------------|
| 40      | Windshield // Repair                                  | Y          |
| 133     | Bumper Rear // Painting                               | Y          |
| 331     | Wheel Alloy Rear Right // Repair                      | Y          |
| 594     | Trunk Lid Interior Coating / Complete Panel / Replace | Y          |

## Damage Pictures



Wheel Alloy Rear Right // Repair-scratch



Bumper Rear // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Windshield // Repair-glass damage

