

# INSPECTION REPORT



End of contract

## GENERAL INFO

File	308934
License plate	2AJX828
Vehicle identification number	W1K1771101J313690
Dossier	2020 314 029
Make	Mercedes A Berline 180 d Busin
Mileage	44689
First registration	20/04/2021
client availability date	01/04/2026
inspectionDate	10/04/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	Y
26	Front // Polish	Y
35	Front Bonnet // Polish	Y
106	Door Rear Left // Polish	Y
136	Bumper Rear // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
165	Roof // Polish	Y
184	Wing Rear Right // Repair & Painting	N
194	Door Rear Right // Repair & Painting	N
219	Door Front Right / Window / Replace	N
225	Side View Mirror Right // Polish	Y
228	Side View Mirror Right / Direction Indicator / Replace	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	N

## Damage Pictures





Damage within Renta-norm-



Front // Polish-scratch



Bumper Front // Smart Repair Large-scratch



Side View Mirror Right / Direction Indicator / Replace-scratch




Door Front Right / Window / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Side View Mirror Right // Polish-scratch



Front Bonnet // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch



Bumper Rear // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Rear Left // Polish-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Door Rear Right // Repair & Painting-scratch + dent



Roof // Polish-Chemical reaction