

INSPECTION REPORT


End of contract

GENERAL INFO

File	318678
License plate	2CEK625
Vehicle identification number	VF3MCYHZUNS098185
Dossier	2021344033
Make	Peugeot 5008 1.5BHdi 96kW Allu
Mileage	100444
First registration	23/06/2022
client availability date	24/07/2026
inspectionDate	05/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
87	Door Front Left / Trim / Replace	N
107	Door Rear Left / Trim / Replace	N
117	Wing Rear Left / Trim / Replace	N
13	Bumper Front // Painting	Y
78	Side View Mirror Left / Direction Indicator / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
194	Door Rear Right // Repair & Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
214	Door Front Right // Repair & Painting	N
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	N

Damage Pictures



Side View Mirror Left / Direction Indicator / Replace-scratch




Bumper Front // Painting-scratch



Door Rear Right // Repair & Painting-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent





Door Front Right // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent




Rocker Panel Left // Smart Repair Medium-scratch + dent



Interior // Repair 1-cracked



Trunk Compartment / Boot Cover / Replace-missing



Rear Bonnet / Rear Window / Replace-scratch



Door Front Left / Trim / Replace-scratch



Door Rear Left / Trim / Replace-scratch



Wing Rear Left / Trim / Replace-scratch