

# INSPECTION REPORT




**End of contract**


## GENERAL INFO

|                               |                               |
|-------------------------------|-------------------------------|
| File                          | 320358                        |
| License plate                 | 2CPV675                       |
| Vehicle identification number | VR3FRHNSTNY602961             |
| Dossier                       | 2022 062 096                  |
| Make                          | Peugeot 308 SW 1.2 130 Allure |
| Mileage                       | 71200                         |
| First registration            | 12/10/2022                    |
| client availability date      | 17/08/2026                    |
| inspectionDate                | 21/08/2026                    |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 2      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | Y       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                            | Acceptable |
|---------|-------------------------------------------------|------------|
| 40      | Windshield // Repair                            | Y          |
| 80      | Door Front Left // Smart Repair Small           | Y          |
| 138     | Bumper Rear / Lower Cover Not Painted / Replace | Y          |
| 190     | Door Rear Right // Smart Repair Small           | Y          |
| 211     | Door Front Right // Smart Repair Medium         | Y          |
| 222     | Side View Mirror Right // Painting              | Y          |
| 310     | Wheel Two Tone Front Left // Repair             | Y          |
| 320     | Wheel Two Tone Rear Left // Repair              | N          |
| 336     | Tyre Rear Right // Replace                      | N          |
| 340     | Wheel Two Tone Front Right // Repair            | N          |
| 346     | Tyre Front Right // Replace                     | N          |

## Damage Pictures



Wheel Two Tone Front Left // Repair-scratch



Side View Mirror Right // Painting-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wheel Two Tone Rear Left // Repair-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Smart Repair Medium-scratch



Door Rear Right // Smart Repair Small-dent



Door Front Left // Smart Repair Small-dent



Windshield // Repair-cracked



Tyre Rear Right // Replace-tear



Tyre Front Right // Replace-tear