

INSPECTION REPORT




End of contract

GENERAL INFO

File	320539
License plate	2AED134
Vehicle identification number	VR3UPHNEKM5814761
Dossier	2020328037
Make	Peugeot 208 1.2PT 100 Active P
Mileage	50811
First registration	05/03/2021
client availability date	25/08/2026
inspectionDate	04/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
13	Bumper Front // Painting	N
35	Front Bonnet // Polish	Y
66	Wing Front Left // Polish	Y
84	Door Front Left // Repair & Painting	N
103	Door Rear Left // Painting	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
213	Door Front Right // Painting	Y
311	Wheel Alloy Front Left // Repair	Y
321	Wheel Alloy Rear Left // Repair	Y
331	Wheel Alloy Rear Right // Repair	Y
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
840	Interior Cleaning // Large	N

Damage Pictures




Wheel Alloy Front Left // Repair-scratch



Wing Front Left // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Wheel Alloy Rear Left // Repair-scratch





Door Rear Left // Painting-scratch




Bumper Front // Painting-scratch



Wheel Alloy Front Right // Repair-scratch





Door Front Right // Painting-scratch




Wheel Alloy Rear Right // Repair-scratch




Door Front Left // Repair & Painting-scratch + dent



Front Bonnet // Polish-Chemical reaction



Roof // Polish-Chemical reaction



Interior Cleaning // Large-stain



Lettering Removal 15min-