

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	281579
License plate	2ALZ108
Vehicle identification number	WBA7K310607J37215
Dossier	2021 040 020
Make	BMW 118i 100kW Aut.
Mileage	69289.00
First registration	07/05/2021
	16/05/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
862	Lettering Removal // XS	N
13	Bumper Front // Painting	N
83	Door Front Left // Painting	N
132	Bumper Rear // Smart Repair Large	N
161	Roof // Smart Repair Medium	N
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	N

Damage Pictures





Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Bumper Rear // Smart Repair Large-scratch



Door Front Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Roof // Smart Repair Medium-dent



Bumper Front // Painting-scratch + dent



Lettering Removal // XS-