

INSPECTION REPORT


End of contract

GENERAL INFO

File	318724
License plate	2FLG409
Vehicle identification number	JTDKBABB60A294747
Dossier	2023177217
Make	Toyota Yar.Cr.1.5 Hyb.85kw Dyn
Mileage	56966
First registration	07/06/2024
client availability date	31/07/2026
inspectionDate	18/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
801	See External Expertise	N
197	Door Rear Right / Trim / Replace	Y
217	Door Front Right / Trim / Replace	Y
330	Wheel Two Tone Rear Right // Repair	Y

Damage Pictures



Door Rear Right / Trim / Replace-scratch




Door Front Right / Trim / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch





See External Expertise-dent