

INSPECTION REPORT



End of contract

GENERAL INFO

File	305860
License plate	2ERX970
Vehicle identification number	JTDKBABB50A292598
Dossier	2023177127
Make	Toyota Yar.Cr.1.5 Hyb.85kw Dyn
Mileage	49791
First registration	09/01/2024
client availability date	17/02/2026
inspectionDate	04/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
38	Front Bonnet / Insulation / Replace	N
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y

Damage Pictures



Damage within Renta-norm-



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Polish-scratch



Front Bonnet / Insulation / Replace-tear