

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	306434
License plate	2BLT303
Vehicle identification number	W1N1671171A593899
Dossier	2021033079
Make	Mercedes GLE 350 de 4M
Mileage	62829
First registration	06/01/2022
client availability date	27/02/2026
inspectionDate	13/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
19	Bumper Front / Lower Cover Not Painted / Replace	N
83	Door Front Left // Painting	Y

## Damage Pictures



Damage within Renta-norm-dent



Bumper Front / Lower Cover Not Painted / Replace-cracked



Door Front Left // Painting-Chemical reaction