

INSPECTION REPORT

End of contract

GENERAL INFO

File	309078
License plate	2FSC637
Vehicle identification number	VR3FRHNS7RY549071
Dossier	2023356424
Make	Peugeot 308 SW 1.2 130 Active
Mileage	11901
First registration	31/07/2024
client availability date	26/03/2026
inspectionDate	26/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
136	Bumper Rear // Polish	Y
222	Side View Mirror Right // Painting	N
627	Front Right Door Interior Coating / Grid Loudspeaker / Replace	Y

Damage Pictures



Side View Mirror Right // Painting-scratch



Bumper Rear // Polish-scratch



Front Right Door Interior Coating / Grid Loudspeaker / Replace-scratch