

INSPECTION REPORT




End of contract

GENERAL INFO

File	307593
License plate	2BFF477
Vehicle identification number	KMHC851CGNU266860
Dossier	2021 161 090
Make	Hyundai Ioniq 1.6GDi Hybride F
Mileage	134804
First registration	29/10/2021
client availability date	09/03/2026
inspectionDate	12/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	Y
38	Front Bonnet / Insulation / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
110	Wing Rear Left // Smart Repair Small	Y
113	Wing Rear Left // Painting	N
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
156	Rear Bonnet // Polish	Y
161	Roof // Smart Repair Medium	Y
183	Wing Rear Right // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	Y
222	Side View Mirror Right // Painting	Y
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
564	Dashboard // Replace Completely	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
621	Front Right Door Interior Coating // Repair	N
631	Rear Left Door Interior Coating // Repair	N
641	Rear Right Door Interior Coating // Repair	N
860	Interior Cleaning // Small	N


Damage Pictures



Damage within Renta-norm-worn





Rear Left Door Interior Coating // Repair-scratch



Wing Rear Left // Smart Repair Small-scratch



Wheel Alloy Rear Left // Repair-scratch



Wing Rear Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front / Spoiler / Replace-scratch







Bumper Front // Painting-scratch





Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch




Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Rear Bonnet // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch




Bumper Rear // Painting-scratch



Rear Right Door Interior Coating // Repair-scratch



Dashboard // Replace Completely-scratch



Front Right Door Interior Coating // Repair-scratch




Side View Mirror Right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch




Wheel Alloy Rear Right // Repair-scratch



Wing Rear Right // Painting-scratch



Rocker Panel Right // Smart Repair Medium-dent



Roof // Smart Repair Medium-dent





Rocker Panel Left // Smart Repair Medium-scratch + dent



Front Bonnet / Insulation / Replace-cracked



Interior Cleaning // Small-stain