

INSPECTION REPORT

End of contract


GENERAL INFO

File	319828
License plate	2CJP884
Vehicle identification number	W1K5M8EB3PN333346
Dossier	2021120002
Make	Mercedes CLA SB 180 Bus.Soluti
Mileage	68619
First registration	12/08/2022
client availability date	07/08/2026
inspectionDate	18/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	








DAMAGES

Damages	Type	Acceptable
162	Roof // Painting	N
169	Rear Bonnet / Spoiler / Replace & Painting	N
16	Bumper Front // Polish	Y
41	Windshield // Replace	Y
86	Door Front Left // Polish	Y
87	Door Front Left / Trim / Replace	Y
91	Rocker Panel Left // Smart Repair Medium	Y
106	Door Rear Left // Polish	Y
114	Wing Rear Left // Repair & Painting	Y
124	Light / Rear left / Replace	Y
125	Light / Rear Left On Rear Bonnet / Replace	N
136	Bumper Rear // Polish	Y
156	Rear Bonnet // Polish	Y
157	Rear Bonnet / Trim / Replace	Y
190	Door Rear Right // Smart Repair Small	Y
219	Door Front Right / Window / Replace	N
236	Wing Front right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	Y
431	Seat Rear Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Bumper Rear // Polish-scratch



Rear Bonnet // Polish-scratch



Light / Rear Left On Rear Bonnet / Replace-scratch




Light / Rear left / Replace-scratch




Rear Bonnet / Trim / Replace-scratch



Door Front Right / Window / Replace-scratch



Wing Front right // Polish-scratch



Bumper Front // Polish-scratch



Door Front Left / Trim / Replace-scratch



Windshield // Replace-scratch



Door Front Left // Polish-scratch



Door Rear Left // Polish-scratch



Wheel Two Tone Rear Left // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch





Seat Rear Left // Repair-scratch



Door Rear Right // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Wing Rear Left // Repair & Painting-scratch + dent



Interior Cleaning // Small-stain



Rear Bonnet / Spoiler / Replace & Painting-scratch



Roof // Painting-scratch