

INSPECTION REPORT

End of contract

GENERAL INFO

File	321097
License plate	PC6631
Vehicle identification number	W0V7H9EJ8L4287054
Dossier	2020034060
Make	Opel Crossland X TD120 Innov.A
Mileage	154145
First registration	24/08/2020
client availability date	28/08/2026
inspectionDate	02/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	N
64	Wing Front Left // Repair & Painting	N
83	Door Front Left // Painting	Y
104	Door Rear Left // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
159	Rear Bonnet / Rear Window / Replace	N
165	Roof // Polish	Y
210	Door Front Right // Smart Repair Small	Y
222	Side View Mirror Right // Painting	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
569	Dashboard / Steering Wheel / Replace	Y

Damage Pictures



Bumper Front / Spoiler / Replace-scratch



Roof // Polish-scratch




Side View Mirror Right // Painting-scratch



Door Front Right // Smart Repair Small-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Door Front Left // Painting-scratch



Wing Front Left // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Dashboard / Steering Wheel / Replace-worn