

INSPECTION REPORT


End of contract

GENERAL INFO

File	319953
License plate	2DLG101
Vehicle identification number	W1NFB5EB2PA876349
Dossier	2022 136 095
Make	Mercedes GLE 350 e 4M
Mileage	135948
First registration	17/04/2023
client availability date	20/08/2026
inspectionDate	26/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
35	Front Bonnet // Polish	Y
41	Windshield // Replace	Y
100	Door Rear Left // Smart Repair Small	Y
110	Wing Rear Left // Smart Repair Small	Y
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
201	Rocker Panel Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
320	Wheel Two Tone Rear Left // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Windshield // Replace-



Wing Rear Right // Polish-scratch



Door Front Right // Polish-scratch



Front Bonnet // Polish-scratch



Door Rear Right // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-dent



Rocker Panel Right // Smart Repair Medium-dent



Wing Rear Left // Smart Repair Small-dent



Door Rear Left // Smart Repair Small-dent



Wheel Two Tone Rear Left // Repair-Chemical reaction