

INSPECTION REPORT



End of contract

GENERAL INFO

File	319137
License plate	2DCW411
Vehicle identification number	VXKUBYHTKP4009327
Dossier	2022 192 156
Make	Opel Corsa 1.5D 102 Edition
Mileage	16165
First registration	07/02/2023
client availability date	30/07/2026
inspectionDate	05/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
84	Door Front Left // Repair & Painting	Y
100	Door Rear Left // Smart Repair Small	Y
110	Wing Rear Left // Smart Repair Small	Y
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	Y
156	Rear Bonnet // Polish	Y
174	Light / Rear Right / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
341	Wheel Alloy Front Right // Repair	Y
541	Interior // Repair 2	Y
773	Interior / A Pillar Lower Cover / Replace	Y

Damage Pictures




Interior / A Pillar Lower Cover / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Light / Rear Right / Replace-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Light / Rear left / Replace-scratch



Bumper Rear // Painting-scratch



Rear Bonnet // Polish-scratch



Door Rear Left // Smart Repair Small-dent



Wing Rear Left // Smart Repair Small-dent



Door Front Left // Repair & Painting-scratch + dent



Interior // Repair 2-missing