

INSPECTION REPORT




End of contract

GENERAL INFO

File	319362
License plate	2BLF347
Vehicle identification number	TMBJ0NX2NY035445
Dossier	2021090142
Make	Skoda Oct.Com.2.0TDI 110kW Cle
Mileage	59385
First registration	03/01/2022
client availability date	03/08/2026
inspectionDate	25/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	3	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	Y
180	Wing Rear Right // Smart Repair Small	Y
341	Wheel Alloy Front Right // Repair	Y

Damage Pictures



Bumper Rear // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Wing Rear Right // Smart Repair Small-dent