

INSPECTION REPORT

End of contract


GENERAL INFO

File	319143
License plate	2AFU507
Vehicle identification number	VF3LCYHZJMS043501
Dossier	2020 286 056
Make	Peugeot 308 SW 1.5BHDi 130 Act
Mileage	82731
First registration	22/03/2021
client availability date	30/07/2026
inspectionDate	10/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
891	Lettering Removal 15min	N
13	Bumper Front // Painting	N
31	Front Bonnet // Smart Repair Small	N
64	Wing Front Left // Repair & Painting	N
80	Door Front Left // Smart Repair Small	N
107	Door Rear Left / Trim / Replace	Y
110	Wing Rear Left // Smart Repair Small	Y
124	Light / Rear left / Replace	N
135	Bumper Rear // Replace & Painting	N
151	Rear Bonnet // Smart Repair Medium	Y
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	Y
180	Wing Rear Right // Smart Repair Small	N
193	Door Rear Right // Painting	Y
205	Rocker Panel Right // Polish	Y
214	Door Front Right // Repair & Painting	N
321	Wheel Alloy Rear Left // Repair	Y
341	Wheel Alloy Front Right // Repair	Y
543	Interior // Ionization Odor	N
549	Interior / Headliner/ Replace	N
569	Dashboard / Steering Wheel / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	N
774	Interior / Side Cover rear Seat / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Rear Bonnet / Rear Window / Replace-scratch



Rear Bonnet // Smart Repair Medium-scratch



Rocker Panel Right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch



Door Rear Left / Trim / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Bumper Front // Painting-scratch





Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Interior / Side Cover rear Seat / Replace-scratch



Door Front Left // Smart Repair Small-dent



Wing Rear Left // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Door Front Right // Repair & Painting-dent



Wing Rear Right // Smart Repair Small-dent



Wing Front Left // Repair & Painting-scratch + dent



Door Rear Right // Painting-bad repair



Light / Rear left / Replace-cracked



Bumper Rear // Replace & Painting-cracked



Interior / Headliner/ Replace-Incinerated



Front Bonnet // Smart Repair Small-Chemical reaction



Interior Cleaning // Small-stain



Dashboard / Steering Wheel / Replace-worn



Lettering Removal 15min-