

INSPECTION REPORT

End of contract


GENERAL INFO

File	317313
License plate	BU6044
Vehicle identification number	W1K1771121J378614
Dossier	2022084017
Make	Mercedes A Sedan 200d 150 Luxu
Mileage	128498
First registration	12/08/2022
client availability date	03/07/2026
inspectionDate	08/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	N
13	Bumper Front // Painting	N
31	Front Bonnet // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	N
106	Door Rear Left // Polish	Y
133	Bumper Rear // Painting	N
201	Rocker Panel Right // Smart Repair Medium	N
214	Door Front Right // Repair & Painting	N
274	Bumper Front / Grid Central / Replace	Y
310	Wheel Two Tone Front Left // Repair	N
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
860	Interior Cleaning // Small	N


Damage Pictures



Bumper Front / Grid Central / Replace-bad position



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Polish-scratch



Wheel Two Tone Front Left // Repair-scratch




Bumper Front // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch




Bumper Rear // Painting-scratch



Front Bonnet // Smart Repair Small-dent



Door Front Right // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Interior Cleaning // Small-dirty



Wheel Two Tone Front Right // Repair-scratch



Tyre Front Right // Replace-tear