

# INSPECTION REPORT



End of contract

## GENERAL INFO

File	309093
License plate	2BRP634
Vehicle identification number	W0VZRHNS5N6805413
Dossier	2021 327 140
Make	Opel Grandland 1.2T 96kW Bus.E
Mileage	90616
First registration	25/02/2022
client availability date	25/03/2026
inspectionDate	30/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
103	Door Rear Left // Painting	Y
111	Wing Rear Left // Smart Repair Medium	Y
124	Light / Rear left / Replace	N
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	Y
431	Seat Rear Left // Repair	Y

## Damage Pictures



Seat Rear Left // Repair-scratch




Wing Rear Left // Smart Repair Medium-scratch




Door Rear Left // Painting-scratch



Door Rear Right // Painting-scratch



Wing Rear Right // Polish-scratch



Light / Rear left / Replace-cracked