

INSPECTION REPORT


End of contract

GENERAL INFO

File	320059
License plate	DH8300
Vehicle identification number	W1NFB0KB5PA935918
Dossier	2023241012
Make	Mercedes GLE 300d 245 4M Busin
Mileage	126582
First registration	19/09/2023
client availability date	12/08/2026
inspectionDate	17/08/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
44	Windshield / Trim / Replace	Y
104	Door Rear Left // Repair & Painting	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
644	Rear Right Door Interior Coating // Replace Completely	Y


Damage Pictures



Windshield / Trim / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Door Rear Left // Repair & Painting-scratch + dent