

# INSPECTION REPORT


End of contract

## GENERAL INFO

File	305853
License plate	2ERY797
Vehicle identification number	JTDKBABB10A293098
Dossier	2023177162
Make	Toyota Yar.Cr.1.5 Hyb.85kw Dyn
Mileage	45370
First registration	09/01/2024
client availability date	17/02/2026
inspectionDate	09/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
103	Door Rear Left // Painting	Y
165	Roof // Polish	Y
320	Wheel Two Tone Rear Left // Repair	Y

## Damage Pictures





Damage within Renta-norm-



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Painting-bad repair



Roof // Polish-Chemical reaction