

INSPECTION REPORT


End of contract


GENERAL INFO

File	318233
License plate	HX4946
Vehicle identification number	YV1XZBWVFN2720234
Dossier	2021134011
Make	Volvo XC40 T4 129 PHEV Ins.Exp
Mileage	125711
First registration	03/01/2022
client availability date	16/07/2026
inspectionDate	20/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
187	Wing Rear Right / Trim / Replace	N
194	Door Rear Right // Repair & Painting	N
197	Door Rear Right / Trim / Replace	N
217	Door Front Right / Trim / Replace	N
64	Wing Front Left // Repair & Painting	N
67	Wing Front Left / Trim / Replace	N
133	Bumper Rear // Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
18	Bumper Front / Spoiler / Replace	N
19	Bumper Front / Lower Cover Not Painted / Replace	Y
35	Front Bonnet // Polish	Y
81	Door Front Left // Smart Repair Medium	N
103	Door Rear Left // Painting	Y
146	Back Side / Reflector L / Replace	N
153	Rear Bonnet // Painting	Y
183	Wing Rear Right // Painting	Y
213	Door Front Right // Painting	N
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y
411	Seat Front Left // Repair	N
421	Seat Front Right // Repair	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
641	Rear Right Door Interior Coating // Repair	N
774	Interior / Side Cover rear Seat / Replace	N

Damage Pictures




Seat Front Left // Repair-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Medium-scratch



Front Bonnet // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Painting-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch



Bumper Front / Spoiler / Replace-scratch



Rear Right Door Interior Coating // Repair-scratch



Seat Front Right // Repair-scratch



Interior / Side Cover rear Seat / Replace-scratch



Wheel Two Tone Front Right // Repair-scratch



Door Front Right // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet // Painting-scratch



Back Side / Reflector L / Replace-scratch



Door Front Right / Trim / Replace-scratch



Door Rear Right / Trim / Replace-scratch



Wing Rear Right / Trim / Replace-scratch



Door Rear Right // Repair & Painting-scratch + dent




Wing Front Left // Repair & Painting-scratch + dent



Wing Front Left / Trim / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch