

INSPECTION REPORT


End of contract

GENERAL INFO

File	320474
License plate	1YVA173
Vehicle identification number	VF3MCYHZJLS258365
Dossier	2020209042
Make	Peugeot 5008 1.5BHdi 96kW Allu
Mileage	98793
First registration	28/12/2020
client availability date	26/08/2026
inspectionDate	14/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
137	Bumper Rear // Replace without painting	N
258	Towing Cover Rear // Replace	N
13	Bumper Front // Painting	Y
33	Front Bonnet // Repair & Painting	Y
38	Front Bonnet / Insulation / Replace	N
91	Rocker Panel Left // Smart Repair Medium	N
102	Door Rear Left // Smart Repair Large	N
107	Door Rear Left / Trim / Replace	N
134	Bumper Rear // Repair & Painting	N
150	Rear Bonnet // Smart Repair Small	Y
159	Rear Bonnet / Rear Window / Replace	Y
186	Wing Rear Right // Polish	Y
187	Wing Rear Right / Trim / Replace	N
193	Door Rear Right // Painting	N
201	Rocker Panel Right // Smart Repair Medium	N
213	Door Front Right // Painting	Y
266	Foglight Rear // Replacement	Y
310	Wheel Two Tone Front Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
336	Tyre Rear Right // Replace	Y
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	N
412	Seat Front Left / Bottom Coating / Replace	Y
556	Central Console / Cover Armrest / Replace Cover Armrest	N

Damage Pictures





Door Rear Left / Trim / Replace-scratch



Rear Bonnet // Smart Repair Small-dent



Rocker Panel Right // Smart Repair Medium-dent



Door Rear Right // Painting-scratch + dent



Front Bonnet // Repair & Painting-scratch + dent



Door Rear Left // Smart Repair Large-scratch + dent




Bumper Rear // Repair & Painting-scratch + dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Foglight Rear // Replacement-cracked



Front Bonnet / Insulation / Replace-tear



Tyre Rear Right // Replace-tear



Tyre Front Right // Replace-tear



Seat Front Left / Bottom Coating / Replace-worn



Wheel Two Tone Front Right // Repair-scratch



Central Console / Cover Armrest / Replace Cover Armrest-scratch



Wheel Two Tone Front Left // Repair-scratch



Bumper Front // Painting-scratch



Door Front Right // Painting-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right / Trim / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wing Rear Right // Polish-scratch



Bumper Rear // Replace without painting-scratch



Towing Cover Rear // Replace-scratch