

INSPECTION REPORT


End of contract

GENERAL INFO

File	321554
License plate	KV4869
Vehicle identification number	W1N1671171A752096
Dossier	2022067010
Make	Mercedes GLE 350de 194 4M Aut
Mileage	72612
First registration	19/07/2022
client availability date	04/09/2026
inspectionDate	08/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		Y	




DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
80	Door Front Left // Smart Repair Small	Y
104	Door Rear Left // Repair & Painting	Y
214	Door Front Right // Repair & Painting	N
320	Wheel Two Tone Rear Left // Repair	N
411	Seat Front Left // Repair	N
417	Seat Front Left / Headrest / Replace	N
532	Trunk Compartment / Side Cover Left / Replace	Y
556	Central Console / Cover Armrest / Replace Cover Armrest	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	Y
860	Interior Cleaning // Small	Y
883	Key Price Range 2 //	N

Damage Pictures



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left // Repair & Painting-scratch



Door Front Left // Smart Repair Small-scratch



Bumper Front // Smart Repair Medium-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Seat Front Left // Repair-scratch




Central Console / Cover Armrest / Replace Cover
Armrest-scratch



Door Front Right // Repair & Painting-scratch + dent



Seat Front Left / Headrest / Replace-tear



Interior Cleaning // Small-stain