

INSPECTION REPORT


End of contract

GENERAL INFO

File	309077
License plate	2FGA856
Vehicle identification number	VXKFRHNP3R1024074
Dossier	2023356296
Make	Opel Astra ST 1.2 81kW Edition
Mileage	24599
First registration	23/05/2024
client availability date	26/03/2026
inspectionDate	26/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
133	Bumper Rear // Painting	Y
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	N
538	Trunk Compartment / Boot Cover / Replace	N
883	Key Price Range 2 //	N

Damage Pictures



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Painting-scratch



Bumper Front // Smart Repair Large-scratch



Wheel Two Tone Front Right // Repair-scratch



Trunk Compartment / Boot Cover / Replace-missing