

INSPECTION REPORT

End of contract

GENERAL INFO

File	317155
License plate	PR9034
Vehicle identification number	VF3MCYHZUNS128490
Dossier	2022094009
Make	Peugeot 3008 BlueHDi 130 Allur
Mileage	163362
First registration	29/11/2022
client availability date	02/07/2026
inspectionDate	06/07/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	






DAMAGES

Damages	Type	Acceptable
32	Front Bonnet // Painting	Y
41	Windshield // Replace	N
80	Door Front Left // Smart Repair Small	Y
210	Door Front Right // Smart Repair Small	Y
340	Wheel Two Tone Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
883	Key Price Range 2 //	N

Damage Pictures



Door Front Left // Smart Repair Small-scratch




Wheel Two Tone Front Right // Repair-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Front Right // Smart Repair Small-dent



Windshield // Replace-glass damage



Seat Front Left / Bottom Coating / Replace-worn



Front Bonnet // Painting-worn