

INSPECTION REPORT


End of contract

GENERAL INFO

File	311833
License plate	2BMH601
Vehicle identification number	W1N1671171A608708
Dossier	2021 193 026
Make	Mercedes GLE 350 de 4M
Mileage	118418
First registration	12/01/2022
client availability date	29/04/2026
inspectionDate	11/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
16	Bumper Front // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	Y
133	Bumper Rear // Painting	Y
201	Rocker Panel Right // Smart Repair Medium	N
320	Wheel Two Tone Rear Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
412	Seat Front Left / Bottom Coating / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
614	Front Left Door Interior Coating // Replace Completely	Y

Damage Pictures



Bumper Front // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Bumper Rear // Painting-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rocker Panel Left // Smart Repair Medium-scratch + dent



Rocker Panel Right // Smart Repair Medium-scratch + dent



Wheel Two Tone Rear Left // Repair-Chemical reaction



Seat Front Left / Bottom Coating / Replace-worn



Front Left Door Interior Coating // Replace Completely-worn