

INSPECTION REPORT

End of contract

GENERAL INFO

File	308823
License plate	2BJK327
Vehicle identification number	YV1XZL4VDN2707926
Dossier	2021168120
Make	Volvo XC40 T2 Momentum Pro Gea
Mileage	184598
First registration	08/12/2021
client availability date	30/03/2026
inspectionDate	31/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
18	Bumper Front / Spoiler / Replace	Y
83	Door Front Left // Painting	Y
104	Door Rear Left // Repair & Painting	Y
107	Door Rear Left / Trim / Replace	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
144	Back Side // Polish	Y
186	Wing Rear Right // Polish	Y
188	Wing Rear Right / Fuel Cover / Replace	Y
196	Door Rear Right // Polish	Y
213	Door Front Right // Painting	Y
274	Bumper Front / Grid Central / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Door Front Right // Painting-scratch




Door Rear Right // Polish-scratch



Wing Rear Right / Fuel Cover / Replace-scratch



Wing Rear Right // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Back Side // Polish-scratch



Door Front Left // Painting-scratch





Bumper Front // Painting-scratch



Bumper Front / Spoiler / Replace-scratch



Door Rear Left / Trim / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Door Rear Left // Repair & Painting-scratch + dent



Bumper Front / Grid Central / Replace-bad position