

# INSPECTION REPORT


End of contract


## GENERAL INFO

File	307834
License plate	MV6446
Vehicle identification number	ZFA250000RG047258
Dossier	2025031004
Make	Fiat Ducato 2.2 Turbo-D 140 L3
Mileage	20167
First registration	07/02/2025
client availability date	11/03/2026
inspectionDate	13/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	







## DAMAGES

Damages	Type	Acceptable
137	Bumper Rear // Replace without painting	N
282	Bumper Rear / Trim Center / Replace	N
194	Door Rear Right // Repair & Painting	N
223	Side View Mirror Right // Replace Not Painted	N
294	Rear Loading Door Left // Repair & Painting	Y
881	Key Price Range 1 //	N

## Damage Pictures




Damage within Renta-norm-scratch




Rear Loading Door Left // Repair & Painting-scratch + dent



Side View Mirror Right // Replace Not Painted-cracked



Door Rear Right // Repair & Painting-dent



Bumper Rear / Trim Center / Replace-scratch + dent





Bumper Rear // Replace without painting-scratch + dent