

INSPECTION REPORT

End of contract


GENERAL INFO

File	308252
License plate	2ABN608
Vehicle identification number	VSSZZZKLZMR053717
Dossier	2020 268 028
Make	Seat Leon ST 1.5TSI 150 FR
Mileage	75540
First registration	10/02/2021
client availability date	17/03/2026
inspectionDate	01/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
41	Windshield // Replace	Y
63	Wing Front Left // Painting	Y
86	Door Front Left // Polish	Y
89	Door Front Left / Window / Replace	N
109	Door Rear Left / Window / Replace	Y
133	Bumper Rear // Painting	Y
159	Rear Bonnet / Rear Window / Replace	Y
184	Wing Rear Right // Repair & Painting	Y
189	Wing Rear Right / Window / Replace	Y
196	Door Rear Right // Polish	Y
199	Door Rear Right / Window / Replace	N
210	Door Front Right // Smart Repair Small	Y
219	Door Front Right / Window / Replace	Y
310	Wheel Two Tone Front Left // Repair	Y
320	Wheel Two Tone Rear Left // Repair	N
330	Wheel Two Tone Rear Right // Repair	N
340	Wheel Two Tone Front Right // Repair	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
540	Interior // Repair 1	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

Damage Pictures



Interior // Repair 1-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear // Painting-scratch



Wheel Two Tone Rear Left // Repair-scratch



Door Rear Left / Window / Replace-scratch



Door Front Left / Window / Replace-scratch



Door Front Left // Polish-scratch



Windshield // Replace-scratch



Wing Front Left // Painting-scratch



Wheel Two Tone Front Left // Repair-scratch



Door Front Right / Window / Replace-scratch



Door Front Right // Smart Repair Small-scratch



Wing Rear Right / Window / Replace-scratch



Door Rear Right / Window / Replace-scratch



Door Rear Right // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch



Wing Rear Right // Repair & Painting-scratch + dent



Wheel Two Tone Front Right // Repair-Chemical reaction