

INSPECTION REPORT


End of contract

GENERAL INFO

File	308389
License plate	1YLY141
Vehicle identification number	YV1ZW72VDM2418779
Dossier	2020260073
Make	Volvo V60 D3 Momentum Pro Gtr.
Mileage	94198
First registration	05/10/2020
client availability date	21/03/2026
inspectionDate	02/04/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
86	Door Front Left // Polish	Y
106	Door Rear Left // Polish	Y
27	Front / Logo / Replace	N
28	Front / Calendar / Replace	N
13	Bumper Front // Painting	Y
31	Front Bonnet // Smart Repair Small	N
41	Windshield // Replace	Y
72	Side View Mirror Left // Painting	N
116	Wing Rear Left // Polish	Y
133	Bumper Rear // Painting	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
184	Wing Rear Right // Repair & Painting	Y
196	Door Rear Right // Polish	Y
216	Door Front Right // Polish	Y
222	Side View Mirror Right // Painting	Y
257	Front / Towing Cover / Replace	N
341	Wheel Alloy Front Right // Repair	N
532	Trunk Compartment / Side Cover Left / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	Y
634	Rear Left Door Interior Coating // Replace Completely	Y

Damage Pictures



Front / Towing Cover / Replace-missing



Wing Rear Left // Polish-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Front Right Door Interior Coating // Replace Completely-scratch



Rear Left Door Interior Coating // Replace Completely-scratch



Bumper Front // Painting-scratch




Front Bonnet // Smart Repair Small-dent



Wing Rear Right // Repair & Painting-scratch + dent



Roof // Polish-scratch





Rear Bonnet // Polish-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Painting-scratch



Rear Bonnet / Rear Window / Replace-scratch



Door Rear Right // Polish-scratch



Door Front Right // Polish-scratch



Side View Mirror Right // Painting-scratch



Wheel Alloy Front Right // Repair-scratch



Windshield // Replace-scratch



Side View Mirror Left // Painting-scratch



Door Front Left // Polish-scratch



Door Rear Left // Polish-scratch



Front / Logo / Replace-cracked



Front / Calendar / Replace-cracked