

INSPECTION REPORT



End of contract


GENERAL INFO

File	315693
License plate	TX8695
Vehicle identification number	W1N2477101J394508
Dossier	2021273003
Make	Mercedes GLA 180d 116 Busin.So
Mileage	142029
First registration	07/06/2022
client availability date	18/06/2026
inspectionDate	23/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
237	Wing Front right / Trim / Replace	N
271	Bumper Front / Trim Left / Replace	N
272	Bumper Front / Trim Right / Replace	N
18	Bumper Front / Spoiler / Replace	N
19	Bumper Front / Lower Cover Not Painted / Replace	N
35	Front Bonnet // Polish	Y
40	Windshield // Repair	Y
61	Wing Front Left // Smart Repair Medium	Y
84	Door Front Left // Repair & Painting	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
136	Bumper Rear // Polish	Y
165	Roof // Polish	Y
186	Wing Rear Right // Polish	Y
193	Door Rear Right // Painting	N
213	Door Front Right // Painting	Y
228	Side View Mirror Right / Direction Indicator / Replace	Y
236	Wing Front right // Polish	Y
421	Seat Front Right // Repair	N
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	N
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Front Bonnet // Polish-scratch



Bumper Front / Lower Cover Not Painted / Replace-scratch




Roof // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch




Bumper Rear // Polish-scratch



Wing Front Left // Smart Repair Medium-scratch



Seat Front Right // Repair-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch



Wing Front right // Polish-scratch



Door Front Right // Painting-scratch






Door Rear Right // Painting-scratch



Wing Rear Right // Polish-scratch



Door Rear Left // Painting-scratch



Bumper Front / Spoiler / Replace-dent



Rocker Panel Left // Smart Repair Medium-dent



Door Front Left // Repair & Painting-scratch + dent




Windshield // Repair-cracked




Trunk Compartment / Boot Cover / Replace-cracked



Interior // Repair 1-Incinerated



Interior Cleaning // Small-stain



Bumper Front // Painting-scratch



Wing Front right / Trim / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front / Trim Right / Replace-scratch