

INSPECTION REPORT



End of contract



GENERAL INFO

File	315230
License plate	JV5943
Vehicle identification number	VR3USHNSSNJ662308
Dossier	2021342098
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	54317
First registration	28/07/2022
client availability date	12/06/2026
inspectionDate	17/06/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
133	Bumper Rear // Painting	N
153	Rear Bonnet // Painting	N
13	Bumper Front // Painting	Y
32	Front Bonnet // Painting	N
38	Front Bonnet / Insulation / Replace	N
41	Windshield // Replace	N
63	Wing Front Left // Painting	N
72	Side View Mirror Left // Painting	Y
83	Door Front Left // Painting	N
103	Door Rear Left // Painting	N
113	Wing Rear Left // Painting	N
117	Wing Rear Left / Trim / Replace	N
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
139	Bumper Rear / Spoiler / Replace	Y
183	Wing Rear Right // Painting	N
187	Wing Rear Right / Trim / Replace	Y
191	Door Rear Right // Smart Repair Medium	Y
214	Door Front Right // Repair & Painting	Y
234	Wing Front right // Repair & Painting	N
237	Wing Front right / Trim / Replace	N
330	Wheel Two Tone Rear Right // Repair	Y
644	Rear Right Door Interior Coating // Replace Completely	Y

Damage Pictures



Wing Rear Left / Trim / Replace-scratch



Wing Rear Left // Painting-scratch



Door Rear Left // Painting-scratch



Door Front Left // Painting-scratch



Side View Mirror Left // Painting-scratch



Wing Front Left // Painting-scratch



Bumper Front // Painting-scratch



Front Bonnet // Painting-scratch



Rear Right Door Interior Coating // Replace Completely-scratch



Wing Front right / Trim / Replace-scratch



Wing Rear Right / Trim / Replace-scratch



Wheel Two Tone Rear Right // Repair-scratch



Door Rear Right // Smart Repair Medium-scratch



Wing Rear Right // Painting-scratch



Wing Front right // Repair & Painting-scratch + dent



Door Front Right // Repair & Painting-scratch + dent



Windshield // Replace-cracked



Front Bonnet / Insulation / Replace-missing



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Rear Bonnet // Painting-scratch



Bumper Rear // Painting-scratch