

INSPECTION REPORT

End of contract

GENERAL INFO

File	321488
License plate	GY5024
Vehicle identification number	VF3MCYHZRLS070603
Dossier	2019333035
Make	Peugeot 3008 BlueHDi 130 Activ
Mileage	169967
First registration	20/05/2020
client availability date	03/09/2026
inspectionDate	07/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	Y
28	Front / Calendar / Replace	Y
32	Front Bonnet // Painting	Y
40	Windshield // Repair	Y
63	Wing Front Left // Painting	Y
67	Wing Front Left / Trim / Replace	Y
83	Door Front Left // Painting	N
91	Rocker Panel Left // Smart Repair Medium	N
104	Door Rear Left // Repair & Painting	N
136	Bumper Rear // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
165	Roof // Polish	Y
181	Wing Rear Right // Smart Repair Medium	N
190	Door Rear Right // Smart Repair Small	Y
210	Door Front Right // Smart Repair Small	Y
216	Door Front Right // Polish	Y
228	Side View Mirror Right / Direction Indicator / Replace	Y
311	Wheel Alloy Front Left // Repair	N
341	Wheel Alloy Front Right // Repair	N
412	Seat Front Left / Bottom Coating / Replace	Y
532	Trunk Compartment / Side Cover Left / Replace	Y
533	Trunk Compartment / Side Cover Right / Replace	Y
540	Interior // Repair 1	N
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
554	Central Console // Replace Completely	Y
568	Dashboard / Ventilation Outlet / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Wing Rear Right // Smart Repair Medium-scratch



Rear Bonnet / Rear Window / Replace-scratch




Bumper Rear // Polish-scratch



Door Front Left // Painting-scratch



Wheel Alloy Front Left // Repair-scratch



Wing Front Left // Painting-scratch




Wing Front Left / Trim / Replace-scratch



Front / Calendar / Replace-scratch



Bumper Front // Painting-scratch



Roof // Polish-scratch



Door Front Right // Smart Repair Small-scratch



Door Front Right // Polish-scratch



Wheel Alloy Front Right // Repair-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch



Trunk Compartment / Side Cover Right / Replace-scratch



Trunk Compartment / Side Cover Left / Replace-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch






Dashboard / Ventilation Outlet / Replace-scratch



Central Console // Replace Completely-scratch




Door Rear Left // Repair & Painting-dent




Door Rear Right // Smart Repair Small-dent



Rocker Panel Left // Smart Repair Medium-scratch + dent



Front Bonnet // Painting-bad repair



Windshield // Repair-cracked



Interior // Repair 1-Incinerated



Interior // Repair 1-Incinerated



Seat Front Left / Bottom Coating / Replace-Incinerated



Interior Cleaning // Small-stain