

INSPECTION REPORT

End of contract

GENERAL INFO

File	303199
License plate	2ABC445
Vehicle identification number	TMBJP9NU2M5019139
Dossier	2020 274 115
Make	Skoda Karoq 1.0TSI 81kW Style
Mileage	97256
First registration	05/02/2021
client availability date	11/02/2026
inspectionDate	05/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
114	Wing Rear Left // Repair & Painting	N
132	Bumper Rear // Smart Repair Large	N
186	Wing Rear Right // Polish	Y
196	Door Rear Right // Polish	Y
12	Bumper Front // Smart Repair Large	N
81	Door Front Left // Smart Repair Medium	Y
136	Bumper Rear // Polish	Y
211	Door Front Right // Smart Repair Medium	N
566	Dashboard / Cover Storage Tray / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures





Damage within Renta-norm-



Interior Cleaning // Small-dirty



Bumper Rear // Polish-scratch




Door Front Right // Smart Repair Medium-scratch



Dashboard / Cover Storage Tray / Replace-scratch




Bumper Front // Smart Repair Large-scratch




Door Front Left // Smart Repair Medium-scratch




Bumper Rear // Smart Repair Large-scratch



Wing Rear Left // Repair & Painting-scratch + dent



Door Rear Right // Polish-bad repair



Wing Rear Right // Polish-bad repair