

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	307338
License plate	2FSC669
Vehicle identification number	VR3FRHNS9RY549072
Dossier	2023356433
Make	Peugeot 308 SW 1.2 130 Active
Mileage	8000
First registration	31/07/2024
client availability date	04/03/2026
inspectionDate	10/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
38	Front Bonnet / Insulation / Replace	Y
54	Headlight / Front left / Replace	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	N
150	Rear Bonnet // Smart Repair Small	N
211	Door Front Right // Smart Repair Medium	N
244	Light / Front Right / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y

## Damage Pictures



Damage within Renta-norm-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Door Front Right // Smart Repair Medium-dent



Rear Bonnet // Smart Repair Small-dent



Front Bonnet / Insulation / Replace-tear



Headlight / Front left / Replace-N comf / out of order



Light / Front Right / Replace-N comf / out of order



Bumper Rear / Lower Cover Not Painted / Replace-scratch