

INSPECTION REPORT




End of contract


GENERAL INFO

File	321442
License plate	2DWC520
Vehicle identification number	YV1XZ14B1K2130549
Dossier	2018 187 079
Make	Volvo XC40 T3
Mileage	100972
First registration	26/02/2019
client availability date	04/09/2026
inspectionDate	14/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
80	Door Front Left // Smart Repair Small	Y
100	Door Rear Left // Smart Repair Small	Y
139	Bumper Rear / Spoiler / Replace	N
412	Seat Front Left / Bottom Coating / Replace	Y
883	Key Price Range 2 //	N

Damage Pictures




Door Front Left // Smart Repair Small-scratch



Door Rear Left // Smart Repair Small-scratch



Bumper Rear / Spoiler / Replace-scratch



Seat Front Left / Bottom Coating / Replace-worn

