

INSPECTION REPORT

End of contract


GENERAL INFO

File	321962
License plate	2CDA993
Vehicle identification number	TMBJC7NY1NF047996
Dossier	2021 148 095
Make	Skoda Enyaq 80
Mileage	162507
First registration	10/06/2022
client availability date	09/09/2026
inspectionDate	22/09/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
213	Door Front Right // Painting	N
217	Door Front Right / Trim / Replace	N
236	Wing Front right // Polish	N
14	Bumper Front // Repair & Painting	N
18	Bumper Front / Spoiler / Replace	N
80	Door Front Left // Smart Repair Small	Y
95	Rocker Panel Left // Polish	Y
100	Door Rear Left // Smart Repair Small	N
136	Bumper Rear // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
165	Roof // Polish	Y
180	Wing Rear Right // Smart Repair Small	Y
188	Wing Rear Right / Fuel Cover / Replace	N
194	Door Rear Right // Repair & Painting	N
228	Side View Mirror Right / Direction Indicator / Replace	N
310	Wheel Two Tone Front Left // Repair	Y
330	Wheel Two Tone Rear Right // Repair	Y
340	Wheel Two Tone Front Right // Repair	N
346	Tyre Front Right // Replace	N
611	Front Left Door Interior Coating // Repair	N
774	Interior / Side Cover rear Seat / Replace	N
860	Interior Cleaning // Small	N

Damage Pictures



Wheel Two Tone Front Right // Repair-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear // Polish-scratch



Wheel Two Tone Rear Right // Repair-scratch




Side View Mirror Right / Direction Indicator / Replace-scratch




Bumper Front / Spoiler / Replace-scratch



Wheel Two Tone Front Left // Repair-scratch




Door Front Left // Smart Repair Small-scratch




Rocker Panel Left // Polish-scratch



Interior / Side Cover rear Seat / Replace-scratch




Front Left Door Interior Coating // Repair-scratch




Door Rear Left // Smart Repair Small-dent



Wing Rear Right // Smart Repair Small-dent





Door Rear Right // Repair & Painting-scratch + dent



Bumper Front // Repair & Painting-scratch + dent



Wing Rear Right / Fuel Cover / Replace-missing



Roof // Polish-Chemical reaction



Tyre Front Right // Replace-tear



Interior Cleaning // Small-stain



Wing Front right // Polish-scratch



Door Front Right / Trim / Replace-scratch



Door Front Right // Painting-scratch