

INSPECTION REPORT


End of contract


GENERAL INFO

File	313608
License plate	JV5940
Vehicle identification number	VR3USHNSSNJ662362
Dossier	2021342025
Make	Peugeot 2008 1.2 PT 130 Allure
Mileage	53717
First registration	26/07/2022
client availability date	22/05/2026
inspectionDate	27/05/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
67	Wing Front Left / Trim / Replace	N
40	Windshield // Repair	Y
75	Side View Mirror Left // Polish	Y
86	Door Front Left // Polish	Y
138	Bumper Rear / Lower Cover Not Painted / Replace	Y
139	Bumper Rear / Spoiler / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
216	Door Front Right // Polish	Y
641	Rear Right Door Interior Coating // Repair	N

Damage Pictures



Rear Right Door Interior Coating // Repair-scratch



Door Front Right // Polish-scratch



Rear Bonnet / Rear Window / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Door Front Left // Polish-scratch




Windshield // Repair-scratch



Side View Mirror Left // Polish-scratch



Wing Front Left / Trim / Replace-scratch



Bumper Front // Smart Repair Large-scratch