

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	307345
License plate	2DDJ595
Vehicle identification number	VXKFPHNPLP1006579
Dossier	2022 192 183
Make	Opel Astra 1.2 81kW Edition
Mileage	70892
First registration	13/02/2023
client availability date	04/03/2026
inspectionDate	11/03/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
134	Bumper Rear // Repair & Painting	N
236	Wing Front right // Polish	Y
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
860	Interior Cleaning // Small	N

## Damage Pictures



Damage within Renta-norm-scratch




Wheel Alloy Front Right // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch





Wheel Alloy Front Left // Repair-scratch



Wing Front right // Polish-bad repair



Bumper Rear // Repair & Painting-cracked



Interior Cleaning // Small-dirty