

INSPECTION REPORT



End of contract

GENERAL INFO

File	308927
License plate	1YRX754
Vehicle identification number	TMBAP7NX3MY069111
Dossier	2020 264 008
Make	Skoda Octavia 1.0 eTec 81kW St
Mileage	86076
First registration	23/11/2020
client availability date	24/03/2026
inspectionDate	31/03/2026

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		Y	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
54	Headlight / Front left / Replace	N
64	Wing Front Left // Repair & Painting	N
271	Bumper Front / Trim Left / Replace	N
80	Door Front Left // Smart Repair Small	Y
91	Rocker Panel Left // Smart Repair Medium	Y
103	Door Rear Left // Painting	Y
113	Wing Rear Left // Painting	Y
133	Bumper Rear // Painting	N
154	Rear Bonnet // Repair & Painting	N
159	Rear Bonnet / Rear Window / Replace	Y
161	Roof // Smart Repair Medium	N
165	Roof // Polish	Y
180	Wing Rear Right // Smart Repair Small	Y
193	Door Rear Right // Painting	N
210	Door Front Right // Smart Repair Small	Y
213	Door Front Right // Painting	Y
222	Side View Mirror Right // Painting	N
311	Wheel Alloy Front Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
336	Tyre Rear Right // Replace	Y
341	Wheel Alloy Front Right // Repair	N
538	Trunk Compartment / Boot Cover / Replace	N
540	Interior // Repair 1	N
549	Interior / Headliner/ Replace	N
611	Front Left Door Interior Coating // Repair	N


Damage Pictures



Interior / Headliner/ Replace-Incinerated



Front Left Door Interior Coating // Repair-Incinerated



Interior // Repair 1-Incinerated



Trunk Compartment / Boot Cover / Replace-missing




Roof // Polish-Chemical reaction




Tyre Rear Right // Replace-worn



Rear Bonnet / Rear Window / Replace-scratch




Bumper Rear // Painting-scratch



Side View Mirror Right // Painting-scratch




Wheel Alloy Front Right // Repair-scratch



Door Front Right // Painting-scratch




Door Front Right // Smart Repair Small-scratch



Door Rear Right // Painting-scratch



Wing Rear Left // Painting-scratch



Door Rear Left // Painting-scratch



Door Front Left // Smart Repair Small-scratch



Wheel Alloy Front Left // Repair-scratch



Wheel Alloy Rear Right // Repair-scratch





Wing Rear Right // Smart Repair Small-dent



Roof // Smart Repair Medium-dent



Rocker Panel Left // Smart Repair Medium-dent



Rear Bonnet // Repair & Painting-scratch + dent



Headlight / Front left / Replace-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front // Replace & Painting-scratch + dent



Wing Front Left // Repair & Painting-scratch + dent